
WIRING DIAGRAM

MDR 18 EC





L1/N - Power supply 230V/50Hz

PE PE conductor

10 V / GND - 10 VDC power supply

E1 - Control voltage Speed input (0-10V)

A1 - Speed output

1/2 - Contact not assigned (with connection of a pressure control)

PWM - PWM speed control

DP - Speed control potentiometer

ODA - Option speed evaluation

n-speed (example: 10 Hz x 60 = 600 rpm)

REP - Repair switch


M - Motor

WIRING DIAGRAM

MDR 18 EC



MDR 18 / 22 / 25 / 31 with pressure and temperature control system EAT EC



KK - terminal box