


## WIRING DIAGRAM

### DSR 35 S



DSR... S with 1 speed



S - control circuit  
X - bridges for high speed  
Y - bridges for low speed

---

# WIRING DIAGRAM

## DSR 35 S



### DSR ... S with star-delta switch (2 speeds)



① to be supplied by the customer

S - control circuit

When using a star-delta switch, remove bridges X and Y on the terminal strip of the DSR ... S. For high speeds.