
WIRING DIAGRAM

DZD 35/4 B



DZD ..B left-hand operation (air extraction) = standard



1 speed

SSK - control circuit


For right-hand operation, swap 2 phases on fan connection.

WIRING DIAGRAM

DZD 35/4 B



DZD .. B with MV 16-1/MV 25-1 motor protection switch




Left-hand operation (air extraction) = standard For right-hand operation, swap 2 phases on fan connection.

WIRING DIAGRAM

DZD 35/4 B



DZD ..B with TR.. 5-step transformer and MV 16-1/MV 25-1 motor protection switch



Left-hand operation (air extraction) = standard For right-hand operation, swap 2 phases on fan connection.