


WIRING DIAGRAM

ER-AP 60 VZ



S1 On (after approx. 50 s)
