
WIRING DIAGRAM

TRE 0,6-2





H1 - Operation (green)

S1 - Switch: On/Off

M1 - Fan motor

K - Connection for external shutter