
WIRING DIAGRAM

ERM 18



ERM.. with on and off switch



- S1 Off switch (to be supplied by the customer)
- S2 On switch (to be supplied by the customer)
- K1 Contactor US 16 T (to be supplied by the customer)