


WIRING DIAGRAM

ESR 31 EC



ESR EC sound-insulated ventilation box with potentiometer ST EC 010




Fuse and main switch provided by customer
Switching the ventilation box on and off only via 0-10 volts

WIRING DIAGRAM

ESR 31 EC



ESR EC sound-insulated ventilation box with potentiometer ST EC 3



- Level 1 – 3-7 V DC
 - Level 2 – 5-9 V DC
 - Level 3 – 10 V DC
- Switching the ventilation box on and off only via 0-10 volts