
## WIRING DIAGRAM

GRD 22





B - Control

- W3 Power cable control (provided by customer)
- K1 Closed soft start
- K1 Open soft stop
- K3 Closed reduction mode active (e.g. night-time operation)
- K3 Open reduction mode inactive
- \* Attention: use K1, K3 gold-plated contacts
- A GRD unit
- W1 Power cable for GRD unit 1.5mm<sup>2</sup> (provided by customer)
- W2 Control cable with sheathing of 0.25 to 0.34mm<sup>2</sup> (provided by customer)
- M Fan motor
- S1 Service switch