


WIRING DIAGRAM

HDR 16



- 1 = low level
 - 2 = high level
 - 3 = highest level
-