


WIRING DIAGRAM

TRE 0,4-2



- H1 - Operation (green)
- S1 - Switch: On/Off
- M1 - Fan motor
- K - Connection for external shutter